



January 1, 2016

**The Georgia Soil and Water Conservation Commission's Equivalent Best Management Practice List (EBMPL)**

Following is a list of Equivalent Best Management Practices as already found in the Fifth Edition of the Manual and on the GADOT QPL's as of January 1<sup>st</sup> 2016. If a product was approved prior to this date and is not on the Equivalent list please provide GSWCC with the documentation stating acceptance. If there is no prior approval, please follow the equivalent BMP process (Appendix A-2 of the Manual) to be included on the EBMPL.

| <b>Sediment Barriers (SD1)</b>       |  |  |  |                         |
|--------------------------------------|--|--|--|-------------------------|
| <b>Source</b>                        | <b>Address</b>   | <b>Contact</b>                               | <b>Product</b>   | <b>Type (Sd1-S/NS)</b>  |
| Assurene Corp.                       | 269 Angla Drive SE<br>Smyrna, GA 30082   | 770-335-4127                                 | Assurene Style ASR 7098  | S                       |
| Belton Industries, Inc               | P.O. Box 127 1205 Hamby Road<br>Belton, SC 29627<br><a href="http://www.beltonindustries.com">www.beltonindustries.com</a> | 864-338-5711<br>800-845-8753<br>800-848-9608 | Beltech 1935   | NS                      |
| Cherokee Manufacturing               | 500 Meldon St. South<br>St. Paul, MN 55075<br><a href="http://www.cherokeemfg.com">www.cherokeemfg.com</a>                 | 912-422-6321<br>800-876-5218                 | CF1200 A<br>CF1500 C   | NS<br>S                 |
| Crown Resources, LLC                 | 2694 Hayes Wilbank Road<br>Toccoa, GA 30577  | 706-779-0287<br>706-779-0336                 | M404   | S                       |
| Construction Fabrics and Supply, LLC | 1603 James P. Rogers Drive<br>Valdosta, GA 31601<br><a href="http://www.siltfenceUSA.com">www.siltfenceUSA.com</a>         | 229-244-0004<br>800-686-1862                 | ConFab CFS-5026  | NS                      |
| DDD Erosion Control, Inc             | P.O. Box 694<br>1383 Industrial Drive<br>Ashburn, GA 31714<br><a href="http://www.3derosion.com">www.3derosion.com</a>     | 229-567-0751                                 | DDDGA36-A<br>Pro-3D/DOT A<br>DDDGA36-C<br>Pro-3D/DOT C<br>GA-CSA | NS<br>NS<br>S<br>S<br>S |
| Erosion Tech, LLC                    | 105 Plant Camelia Road<br>Juliette, GA 31046<br><a href="http://www.erosiontechusa.com">www.erosiontechusa.com</a>         | 478-994-6009                                 | ET-GA-A<br>ET-GA-C<br>ET-C System                                | NS<br>S<br>S            |

|                                  |  |                              |  |   |
|----------------------------------|--|------------------------------|--|---|
| Filtrexx                         | 35481 Grafton Eastern Rd<br>Grafton OH 44044<br><a href="http://www.filtrexx.com">www.filtrexx.com</a>                               | 440-926-2607                 | Filtrexx Filter Soxx<br>(≥18 inch)   | NS  |
| Geo Tex, LLC                     | P.O. Box 46<br>452 Main Street<br>Enigma, GA 31749   | 229-533-5785<br>229-533-9217 | ASH-SFC-36<br>PSFG-36B<br>GF-55<br>GEOPAC-A<br>GEOPAC-450<br>GFG-A<br>GFG-C<br>GFG-CF<br>GFG-B                       | S<br>NS<br>NS<br>NS<br>NS<br>NS<br>S<br>S<br>NS |
| Gro-Green Solutions Georgia, LLC | 315 Corporate Parkway<br>Suite 120<br>Macon, GA 31210  | 478-745-1611                 | Gro C-POP<br>C-POP The Original System<br>GA-A-gg1<br>GA-C-gg1<br>GA-A-gg2<br>GA-C-gg2                               | S<br>S<br>NS<br>S<br>NS<br>S                    |
| Global Erosion Products, LLC     | 3533 Liberty Ridge Trail<br>Marietta, GA 30062   | 404-402-1782                 | GEP-A  | NS  |
| Hanes Geo Components             | 815 Buxton Street<br>Winston Salem, NC 27101<br><a href="http://www.hanesgeo.com">www.hanesgeo.com</a>                               | 336-747-1600<br>888-239-4539 | TerraTex GASF-A<br>TerraTex GASF-AF<br>Terra Tex GASF-C<br>TerraTex GASF-CI<br>TerraTex GASF-CSF (Silt Fence System) | NS<br>NS<br>S<br>S<br>S                         |
| L & M Bag and Supply Co. Inc.    | P.O. Box 640<br>1800 Springhead Church<br>Willacoochee, GA 31650<br><a href="http://www.landmsupplyco.com">www.landmsupplyco.com</a> | 912-534-6071<br>800-948-7870 | LMSF-A100<br>LMSF-C200   | NS<br>S   |
| Landscape Depot                  | 185 Walter Way<br>Fayetteville, GA 30214<br><a href="http://www.landscape-depot.com">www.landscape-depot.com</a>                     | 770-719-3330<br>877-719-3330 | LDI-A<br>LDI-C   | NS<br>S   |
| NGC                              | 256 Paper Lane<br>Clarksville, GA 30253  | 770-839-6632                 | POP-C  | S   |

|                                      |   |   |   |               |
|--------------------------------------|---|---|---|---------------|
| Thrace-LINQ, Inc.                    | 2550 W. 5th North Street<br>Summerville, SC 29483<br><a href="http://www.thracelinq.com">www.thracelinq.com</a>                       | 843-875-5800<br>800-445-4675  | GTF-400EO   | S             |
| Propex Operating Company, LLC        | 1110 Market Street,<br>Suite 300<br>Chattanooga, TN 37402<br><a href="http://www.propexglobal.com">www.propexglobal.com</a>           | 423-899-7619<br>800-621-1273  | Geotex 106F (Formerly:Propex-1198)<br>Geotex 102F (Formerly:Propex-2019)<br>Geotex 111F (Formerly:Geotex 111) | S<br>NS<br>S  |
| Robert Page and Company              | PO Box 2088<br>Griffin GA 30224<br><a href="http://www.cpopsystems.com">www.cpopsystems.com</a>                                       | 770-652-4601  | C-POP   | S             |
| Silt-Saver, INC                      | 1094 Culpepper Dr.<br>Conyers GA 30094  | Toll-free: 1-800-382-SILT<br>770-388-7818<br><a href="http://www.siltsaver.com">www.siltsaver.com</a> | Belted Silt Retention Fence (system) BSRF   | S             |
| Skaps Industries                     | 316 S. Holland Drive<br>Pendergrass, GA 30567<br><a href="http://www.skaps.com">www.skaps.com</a>                                     | 706-639-3440  | M404  | S             |
| SunCoast Fabrics                     | 1055 Windward Ridge Pkwy<br>Suite 170<br>Alpharetta, GA 30005<br><a href="http://www.suncoastfabrics.com">www.suncoastfabrics.com</a> | 678-339-9942<br>800-366-5003  | SCF 1200<br>SCF 1500  | NS<br>S       |
| Willacoochee Industrial Fabrics, Inc | P.O. Box 599<br>769 W. Main St.<br>Willacoochee, GA 31650<br><a href="http://www.winfabusa.com">www.winfabusa.com</a>                 | 912-534-5757  | 1215 Silt Fence<br>1216 Silt Fence<br>2098 Silt Fence   | NS<br>NS<br>S |

| <b>Check Dam (Cd)</b> |  |                |                                    |                                   |
|-----------------------|--|----------------|------------------------------------|-----------------------------------|
| <b>Source</b>         | <b>Address</b>   | <b>Contact</b> | <b>Product</b>                     | <b>Type<br/>(Cd-<br/>S/Hb/Fs)</b> |
| Filtrexx              | 35481 Grafton Eastern Rd<br>Grafton OH 44044<br><a href="http://www.filtrexx.com">www.filtrexx.com</a> | 440-926-2607   | Filtrexx Filter Soxx<br>(≥18 inch) | Fs                                |

| Channel Stabilization (Ch)               |  |  |                            |                 |
|--|--|--|----------------------------|-----------------|
| Source                                   | Address  | Contact  | Product                    | Type (Ch-1/2/3) |
| American Excelsior Company               | 850 Avenue H East<br>PO Box 5067<br>Arlington, TX 76011<br><a href="http://www.curlex.com">www.curlex.com</a>                      | 817-385-3500<br>800-777-7645<br>888-352-9582<br>715-236-5643 | Recyclex TRM               | 2               |
|  |  |  | Curlex Enforcer            | 2               |
|  |  |  | Curlex II Natural Aspen    | 1               |
|  |  |  | Curlex II QuickGRASS Green | 1               |
|  |  |  | Curlex III Natural Aspen   | 1               |
| Colbond Geosynthetics, Inc.              | PO Box 1057<br>1301 Sand Hill Road<br>Enka, NC 28728<br><a href="http://www.colbond-usa.com">www.colbond-usa.com</a>               | 828-665-5000<br>800-365-7391                                 | ENKAMAT 7020               | 2               |
| Contech Construction Products            | 6825 Jimmy Carter Blvd<br>Suite 1800<br>Norcross, GA 30071<br><a href="http://www.contech-epi.com">www.contech-epi.com</a>         | 770-409-0814   | Contech TRM C-45           | 2               |
| East Coast Erosion Control Blankets, LLC | 443 Bricker Road<br>Bernville, PA 19506<br><a href="http://www.erosionblankets.com">www.erosionblankets.com</a>                    | 610-488-8496<br>800-582-4005                                 | T-Recs TRM                 | 2               |
|  |  |  | ECP-3 TRM                  | 2               |
|  |  |  | ECP-2                      | 2               |
|  |  |  | ECSC-3                     | 2               |
|  |  |  | ECC-3                      | 2               |
|  |  |  | ECP-2                      | 2               |
| ECX-2 Double Net                         | 1  |  |                            |                 |
| Erosion Tech, LLC                        | 105 Plant Camelia Road<br>Juliette, GA 31046<br><a href="http://www.erosiontechusa.com">www.erosiontechusa.com</a>                 | 478-994-6009<br>866-894-7458                                 | ETPP-10                    | 2               |
|  |  |  | ETC-100                    | 1               |
|  |  |  | ETX-2                      | 1               |
| Tensar North American Green              | 5401 St. Wendel-Cynthiana Rd.<br>Poseyville, IN 47633<br><a href="http://www.nagreen.com">www.nagreen.com</a>                      | 812-867-6632<br>800-772-2040                                 | C-125                      | 1               |
|  |  |  | P550                       | 2               |
|  |  |  | SC250                      | 2               |
|  |  |  | C350                       | 2               |
|  |  |  | P300                       | 2               |
| Profile Products, LLC                    | 750 Lake Cook Road<br>Suite 440<br>Buffalo Grove, IL 60089<br><a href="http://www.profileproducts.com">www.profileproducts.com</a> | 603-760-2946<br>866-325-6262                                 | ENKAMAT 7020               | 2               |



January 1, 2016

|                                     |   |                              |   |                  |
|-------------------------------------|---|------------------------------|---|------------------|
| Propex Operating Company, LLC       | 1110 Market Street<br>Suite 300<br>Chattanooga, TN 37402<br><a href="http://www.propexglobal.com">www.propexglobal.com</a>            | 423-553-2450                 | Landlok® 450<br>PYRAMAT® Tan/Green          | 2<br>2           |
| Southern Environmental Conservation | 902 Main Ave<br>Suite A<br>Northport, AL 35476<br><a href="http://www.southernenvironmental.net">www.southernenvironmental.net</a>    | 205-292-5660<br>866-252-4486 | SEC-P2                                      | 2                |
| U.S. Erosion Control Products       | 1034 Albany Ave. West<br>Pearson, GA 31642<br><a href="http://www.landsupplyco.com">www.landsupplyco.com</a>                          | 912-534-6071<br>800-948-7870 | US-2P10<br>US-2P12<br>US-2X                 | 2<br>2<br>1      |
| Webtec, Inc.                        | PO Box 19729<br>Charlotte, NC 28219<br><a href="http://www.info@webtechgeos.com">www.info@webtechgeos.com</a>                         | 704-398-0954<br>800-438-0027 | Terra Guard 45P                             | 2                |
| Western Excelsior                   | 4609 E. Boonville New<br>Harmony Rd<br>Evansville, IN 47725<br><a href="http://www.westernexcelsior.com">www.westernexcelsior.com</a> | 866-540-9810                 | PP5-10<br>PP5-12<br>EXCEL S-2<br>EXCEL SS-2 | 2<br>2<br>1<br>1 |
| Winters Excelsior Company, Inc.     | PO Box 39<br>77 Holly Rd<br>McWilliams, AL 36753<br><a href="http://www.wintersexcelsior.com">www.wintersexcelsior.com</a>            | 251-746-2173<br>800-248-7237 | WintersFiber™ HV<br>Winters Coir            | 1<br>1           |

| <b>Inlet Protection (Sd2)</b> |  |  |                                       |             |
|-------------------------------|--|--|---------------------------------------|-------------|
| <b>Source</b>                 | <b>Address</b>                         | <b>Contact</b>   | <b>Product</b>                        | <b>Type</b> |
| Silt-Saver, INC               | 1094 Culpepper Dr.<br>Conyers GA 30094 | Toll-free: 1-800-382-SILT<br>770-388-7818<br>www.siltsaver.com | The Silt Saver®<br>(Frame and Filter) | Sd2-Alt     |

| <b>Slope Stabilization (SS)</b>            |   |  |                                    |              |
|--|---|--|------------------------------------|--------------|
| <b>Source</b>                              | <b>Address</b>  | <b>Contact</b>   | <b>Product</b>                     | <b>Type</b>  |
| American Excelsior Company                 | 850 Avenue H East<br>PO Box 5067<br>Arlington, TX 76011<br><a href="http://www.curlex.com">www.curlex.com</a>                 | 817-385-3500<br>800-777-7645<br>888-352-9582<br>715-236-5643 | AEC Premier Straw – Single Net     | RECP         |
|  |   |  | Curlex I QuickGRASS Green          | RECP         |
|  |   |  | Curlex II Natural Aspen            | RECP         |
|  |   |  | Curlex II QuickGRASS Green         | RECP         |
|  |   |  | Curlex III Natural Aspen           | RECP         |
|  |   |  | Curlex Enforcer<br>Curlex Net Free | RECP<br>RECP |
| American Excelsior Company                 | 850 Avenue H East<br>PO Box 5067<br>Arlington, TX 76011<br><a href="http://www.curlex.com">www.curlex.com</a>                 | 817-385-3500<br>800-777-7645<br>888-352-9582<br>715-236-5643 | Excel Fiber Mulch II               | HECP         |
|  |   |  | Excel Fiber Mulch II w/ TAC        | HECP         |
|  |   |  | Bindex Wood                        | HECP         |
|  |   |  | Bindex Wood WT                     | HECP         |
|  |   |  | Bindex Blend<br>Bindex Blend WT    | HECP<br>HECP |
| Applegate Insulation Systems, Inc.         | 762 Stonecypher St.<br>Cornelia, GA 30531<br><a href="http://www.applegateinsulation.com">www.applegateinsulation.com</a>     | 706-778-2919<br>888-427-7534                                 | Premium Quality Paper Mulch        | HECP         |
| CANFOR/Fiber Marketing International, Inc. | 2806 NE Sunset Blvd<br>Suite A<br>Renton, WA 98056<br><a href="http://www.fibermarketing.com">www.fibermarketing.com</a>      | 425-277-9966<br>800-426-6002                                 | EcoFibre Wood Fiber Mulch          | HECP         |
|  |   |  | EcoFibre + TAC Wood Fiber Mulch    | HECP         |
| Carolina Precision Fibers                  | 145 Factory Street<br>Ronda, NC 26870<br><a href="http://www.carolinaprecisionfibers.com">www.carolinaprecisionfibers.com</a> | 336-527-4140<br>866-476-3278                                 | Mulch & Grow<br>Terrain Lok BFM    | RECP<br>RECP |



|                                  |  |                                      |   |   |
|----------------------------------|--|--------------------------------------|---|---|
| Carolina Precision Fibers        | <p>145 Factory Street<br/>Ronda, NC 26870<br/><a href="http://www.carolinaprecisionfibers.com">www.carolinaprecisionfibers.com</a></p> | <p>336-527-4140<br/>866-476-3278</p> | <p>Mulch &amp; Grow 100% Wood Mulch<br/>Mulch &amp; Grow 70/30 Wood Blend<br/>Mulch &amp; Grow Premium<br/>Mulch &amp; Grow Hybrid 70/30 Blend<br/>Mulch &amp; Grow Bonded Fiber Matrix (BFM)</p> | <p>HECP<br/>HECP<br/>HECP<br/>HECP<br/>HECP</p>                   |
| East Coast Erosion Blankets, LLC | <p>443 Bricker Road<br/>Bernville, PA 19506<br/><a href="http://www.erosionblankets.com">www.erosionblankets.com</a></p>               | <p>610-488-8496<br/>800-582-4005</p> | <p>HY-C1</p>  | <p>HECP</p>   |
| East Coast Erosion Blankets, LLC | <p>443 Bricker Road<br/>Bernville, PA 19506<br/><a href="http://www.erosionblankets.com">www.erosionblankets.com</a></p>               | <p>610-488-8496<br/>800-582-4005</p> | <p>ECS-1 Single Net<br/>ECS-2 Double Net<br/>ECSC-2 Double Net<br/>ECX-1 Single Net<br/>ECX-2 Double Net<br/>ECC-3<br/>ECS-2D<br/>ECS-1D</p>  | <p>RECP<br/>RECP<br/>RECP<br/>RECP<br/>RECP<br/>RECP<br/>RECP</p> |
| Erosion Tech                     | <p>105 Plant Camelia Rd<br/>Juliette, GA 31046<br/><a href="http://www.erosiontech.usa.com">www.erosiontech.usa.com</a></p>            | <p>478-994-6009<br/>866-894-SILT</p> | <p>ET-RS1 Single Net<br/>ET-RS2 Double Net<br/>ETX-2</p>  | <p>RECP<br/>RECP<br/>RECP</p>                                     |
| Industrial Fabrics Inc.          | <p>510 O'Neal Lane Extension<br/>Baton Rouge, LA 70819<br/><a href="http://www.greensolutions.us">www.greensolutions.us</a></p>        | <p>225-273-9600<br/>800-848-4500</p> | <p>GreenSolutions Single Net Straw (SNS-1)<br/>GreenSolutions Double Net Straw (DNS-2)</p>  | <p>RECP<br/>RECP</p>  |
| Mat Inc.                         | <p>12402 Highway 2<br/>Floodwood, MN 55736<br/><a href="http://www.soilguard.com">www.soilguard.com</a></p>                            | <p>218-476-2033<br/>888-477-3028</p> | <p>Soil Guard Bonded Fiber Matrix<br/>Flex Guard<br/>Spray Guard</p>  | <p>RECP<br/>RECP<br/>RECP</p>                                     |
| Mulch & Seed Innovations, LLC    | <p>7265 Alabama Highway 9 South<br/>Centre, AL 35960<br/><a href="http://www.mulchandseed.com">www.mulchandseed.com</a></p>            | <p>256-927-8823</p>                  | <p>GEO Skin Cotton Hydromulch</p>   | <p>HECP</p>   |



|  |  |   |   |  |
|--|--|---|---|--|
| <p>Profile Products, LLC</p>               | <p>750 Lake Cook Rd<br/>Suite 440<br/>Buffalo Grove, IL 60089<br/><a href="http://www.profileproducts.com">www.profileproducts.com</a></p> | <p>847-215-1144<br/>800-366-1180<br/>800-508-8681</p> | <p>Futterra® Green<br/>Futterra® Natural<br/>Futterra® High<br/>Performance-Flexible<br/>Growth Medium (HP-<br/>FGM™)<br/>Hydro-Blanket® Bonded<br/>Fiber Matrix (BFM)<br/>Terra-Matrix™ SMM<br/>Stabilized Mulch Matrix-<br/>Wood Fiber Blanket<br/>EcoAegis® BFM,<br/>Bonded Fiber Matrix-<br/>Wood Fiber Blanket<br/>EcoMatrix®-EcoMatrix™<br/>Engineered Fiber Matrix<br/>(EFM)<br/>EcoFibre® plus Tackifier<br/>– Wood Fiber Blanket<br/>ProMatrix™ - EFM,<br/>Engineered Fiber Blanket<br/>Eco Blend Wood Fiber</p> | <p>RECP<br/>RECP<br/>RECP<br/><br/>RECP<br/><br/>RECP<br/><br/>RECP<br/><br/>RECP<br/>RECP<br/>RECP<br/>RECP</p> |
| <p>Propex Operating<br/>Company, LLC</p>   | <p>1110 Market Street, Suite 300<br/>Chattanooga, TN 37402<br/><a href="http://www.propexglobal.com">www.propexglobal.com</a></p>          | <p>770-941-1711<br/>800-445-7732</p>                  | <p>Landloc S-1<br/>Landloc S-2</p>  | <p>RECP<br/>RECP</p>   |
| <p>TensarCorp/North<br/>American Green</p> | <p>5401 St. Wendel-Cythiana Rd.<br/>Poseyville, IN 47633<br/><a href="http://www.nagreen.com">www.nagreen.com</a></p>                      | <p>812-867-6632<br/>800-772-2040</p>                  | <p>HydraGS (GeoSkin)</p>  | <p>HECP</p>  |
| <p>TensarCorp/North<br/>American Green</p> | <p>5401 St. Wendel-Cythiana Rd.<br/>Poseyville, IN 47633<br/><a href="http://www.nagreen.com">www.nagreen.com</a></p>                      | <p>812-867-6632<br/>800-772-2040</p>                  | <p>S-75<br/>S-150<br/>HydraCM<br/>HydraGT (GeoSkin XT)<br/>HydraCX</p>  | <p>RECP<br/>RECP<br/>RECP<br/>RECP<br/>RECP</p>  |
| <p>USG Corporation</p>                     | <p>125 S. Franklin St.<br/>Chicago, IL 60606<br/><a href="http://www.gypsumsolutions.com">www.gypsumsolutions.com</a></p>                  | <p>678-546-9817<br/>312-214-5896<br/>800-621-9523</p> | <p>Enviro-Shield Brand<br/>Bonded Fiber Matrix</p>  | <p>HECP<br/>HECP</p>   |

|                                 |   |                              |  |                                      |
|---------------------------------|---|------------------------------|--|--------------------------------------|
| U.S. Erosion Control Products   | 1034 Albany Ave. West<br>Pearson, GA 31642<br><a href="http://www.landsupplyco.com">www.landsupplyco.com</a>                      | 912-948-5201                 | US-1S<br>US-2S<br>US-1X<br>US-2X<br>US-2SC   | RECP<br>RECP<br>RECP<br>RECP<br>RECP |
| Western Excelsior Corporation   | 4609 E Boonville New Harmony Rd<br>Evansville, IN 47725<br><a href="http://www.westernexcelsior.com">www.westernexcelsior.com</a> | 866-540-9810<br>970-682-4594 | EXCEL S-2<br>EXCEL SR-1<br>EXCEL SS-2<br>EXCEL SD-3                                  | RECP<br>RECP<br>RECP<br>RECP         |
| Western Excelsior Corporation   | 4609 E Boonville New Harmony Rd<br>Evansville, IN 47725<br><a href="http://www.westernexcelsior.com">www.westernexcelsior.com</a> | 866-540-9810<br>970-682-4594 | 100% Aspen Excelsior Mulch<br>Turbo Mulch  | HECP<br>HECP                         |
| Winters Excelsior Company, Inc. | PO Box 39<br>77 Holly Road<br>McWilliams, AL 36753<br><a href="http://www.wintersexcelsior.com">www.wintersexcelsior.com</a>      | 251-746-2173<br>800-248-7237 | WinterStraw™<br>WinterStraw™HV<br>WintersChoice™<br>WintersFiber™<br>WintersFiber™HV | RECP<br>RECP<br>RECP<br>RECP<br>RECP |

| <b>Tackifiers (Tac)</b>      |   |                              |                                  |                             |
|------------------------------|---|------------------------------|----------------------------------|-----------------------------|
| <b>Source</b>                | <b>Address</b>  | <b>Contact</b>               | <b>Product</b>                   | <b>Type<br/>(1/2/3/4/5)</b> |
| Finn Corporation             | 9281 LeSaint Drive<br>Fairfield, OH 45014<br><a href="http://www.finncorp.com">www.finncorp.com</a> | 513-874-2818<br>800-543-7166 | Finn A500 Hydro-Stik             | 2                           |
| Mat Inc.                     | 12402 Highway 2<br>Fleetwood, MN 55736<br><a href="http://www.soilguard.com">www.soilguard.com</a>  | 218-476-2033<br>888-477-3028 | Super-Tack                       | 2                           |
| Hercules Environmental, Inc. | 6596 New Peachtree Rd<br>Doraville, GA 30340  | 770-455-6551                 | Hercules Soiloc-E                | 2                           |
| Profile Products, LLC        | 750 Lake Crook Road<br>Suite 440<br>Buffalo Grove, IL 60089   | 847-215-1144<br>800-366-1180 | Terra Mulch Tacking Agent III    | 3                           |
|                              |   |                              | CONWED CON-TAC Organic Tackifier | 2                           |